

ARROW RESINS

3D Coating




How To Use ?



- Use clean workspace, wear gloves and mask
- Mix 2 parts resin with 1 part hardener by weight
- Stir slowly for few minutes until fully blended and clear



- Add pigments or inclusions if desired, mix gently
- Pour slowly into mold or into surface, spread evenly




- Use heat gun or torch briefly to remove air bubbles if needed.
- Let cure undisturbed for 5 hours, cover to protect from dust. Fully cure after 8 hours.

"From furniture to flooring, art to décor, our resin-hardener set transforms every surface into a crystal-clear, high-gloss shield that endures high heat"



High Heat capacity



Glossy Clear Coating



Bubbles Free finish



Non Yellowish for lasting clarity



Low VOCs



Pot life & Drying time at 25°C

Pot life	25-30 Min
Surface dry	2 Hours
Hard dry	5-6 Hours

Mixing ratio by weight	2R : 1H
Shelf life	2 Years
Heat Resistance	50-55 °C

Available Packaging Formats

- 1.5 kg, 7.5 Kg, 15 kg
- Bulk packaging supplied in 5 Kg, 10 Kg or 20 Kg cans.



- Keep away from children & Pets.
- Always protect your skin, and eyes.
- Do not ingest or inhale fumes.
- Store tightly sealed in a cool-dry place.