


ART RESIN
3:1



How To Use ?



- Use clean workspace, wear gloves and mask
- Mix 3 parts resin with 1 part hardener by weight
- Stir slowly for 3–5 minutes until fully blended and clear
- Add pigments or inclusions if desired, mix gently
- Pour slowly into mold or into surface, spread evenly
- Use heat gun or torch briefly to remove air bubbles
- Let cure undisturbed for 10-12 hours, cover to protect from dust. Fully cure after 20 hours.
- Demold carefully, trim or polish if needed



Crystal Clear & Glossy look



Long Pot-Life
Upto 45 minutes



Cure time
12 hours



Bubbles Free
finish



Non Yellowish for
lasting clarity

Pot life & Drying
time at 25°C

Pot life	40 - 45 Min
Surface dry	3-4 Hours
Touch dry	12 Hours
Hard dry	24 Hours

Pour Thickness	10-12 mm
Mix Viscosity (cP) at 25°C	4000-5000
Mixing ratio by weight	3R : 1H
Shelf life	2 Years

Available Packaging Formats

- 4 kg, 8 Kg, 16 kg
- Bulk packaging supplied in 10 Kg or 20 Kg cans.



- Keep away from children & Pets.
- Always protect your skin, and eyes.
- Do not ingest or inhale fumes.
- Store tightly sealed in a cool-dry place.